



FLYERS ASSOCIATION NEWS

Number 97-2

August 1997



Beech aircraft Serial No. 1. Completely restored and on display at Staggerwing Museum, site of Duke 1997 fly-in, September 25 - 27, Tullahoma, Tennessee

President
Bill Passey
Mesa, AZ

Vice President
Max Cohen
Dunwoody, GA

Secretary-Treasurer
Marge Gorman
Mansfield, OH

Getting down toward the end of our supply

Three original Duke commercials from 1960 - 1980. 30 minutes - VCR copies are \$11.95 postpaid in US or Canada. Contact Jim Gorman.

Spare parts on hand for your Duke

| | |
|----------------------------------|--|
| 1 - Generator | 2 - Oil Coolers |
| 1 - Starter | 1 - Magneto |
| 1 - Pilot Hydraulic Seat Control | 1 - Lycoming Exhaust Pipe Part No. 77429 |
| 1 - 5 x 6.0 Nose Wheel Tire | 1 - 19 x 6.75-8 Main Gear Tire |
| 4 - Prop Brush 3E1206-2 | 1 - 19 x 6.75-8 Main Gear Tube |

The arrangement we have with Aircraft Systems, 5187 Falcon Road, Rockford, IL 61109, is they will ship an O/H generator, starter, or magneto to you by UPS or Federal Express. You return to them (same day) your part to them. They will overhaul, charging for work done and the item becomes association emergency part. Phone number 815/399-0225.

For oil cooler contact Bill Passey, 602/969-2291 (office).

For other items contact Jim Gorman 419/755-1223 (office).

Remember overhaul of generator at 900 hours will cost you about 85% more than O/H at 500 hours.

Propellers

Recently Marge and I represented the World Beechcraft Society at a meeting with Hartzell Propeller, FAA, and other interested parties regarding a proposed AD on their early propellers manufactured in the 1950's and 60's. (This does not apply to the Duke.)

Of interest to us Duke owners were the comments on "fly-by-night" propeller shops who were giving paper overhauls.

Also, the startling revelation some of the 40 year old props had never been overhauled. Seems people overhaul their engine and stick the same old prop back on.

Attached is a list of Hartzell distributors and overhaul facilities. It may be much less expensive in the long run to use a factory authorized O/H facility.

Turbochargers

While on the subject of overhaul shops, *Aviation Safety*, July 1997 brings up a subject which should concern us all. This issue relates how improper repairs to a Duke turbocharger caused a single engine approach which resulted in a fatal crash. In February 1995 another Duke made a forced landing due to power loss.

Had a chance to speak with Mr. Don Winters of Allied Signal (Garrett) manufacturers of the Duke turbocharger. They hold the only PMA for turbo parts and maintain overhaul facilities in Torrance, California. As important as this item is to safe operation having anyone else do the overhaul may be short-sighted. Go back and read Issue 96-1, Page 3.

Have also included in this issue, their distributor list.

Moral of both stories is have your overhauls done by organizations who will stand behind their work and are authorized by the manufacturer.

* * * * *

According to published reports 12 turbo twin Cessna's (i.e. 340, 414, 421) have crashed during the past three years resulting in 24 fatalities.

As noted in *Aviation Consumer* poor design (turbo mounted on airframe instead of engine) is the root of the problem along with questionable maintenance. Failure of the exhaust system causing subsequent failure of cross feed fuel lines aft of firewall is believed to be the cause of fires.

We should be thankful our aircraft was designed by Beech and not Cessna.

However, Alan Caddey, a metallurgical engineer believes operation of TIT in excess of 1600 degrees F. (871 degrees C) will cause corrosion of stainless steel. "The Twin Cessna Flyer" of New Haven, IN has given us permission to reprint his thoughts. Discussing this with Ron Gross of Raytheon, it appears it would be wise to keep the TIT at 850 degrees C. (1562 degrees F.) to insure long life on exhaust components. A new exhaust stack for the B60 is \$1700.00. That will buy a lot of fuel.

WELCOME NEW MEMBERS

| | | | |
|--|-------|--------------------------------------|-------|
| Bill Nedell Boulder, Co | P-427 | Jack Hurula Jackson, MI | P-444 |
| Deason Dunagan Huntsville, Al | | Quentin Ence St. George, UT | P-188 |
| David E. Trant Baytown, TX | P-451 | Bob Stan Dayton, OH | P-404 |
| Martin Hagensieker Bad Essen, Germany | | Capt. Peter Edwards Hong Kong | |
| Don Douglas Calgary, Alberta | P-363 | Dr. Keith Mullenger St. Louis, MO | |
| Ron Comeavlt Sault St. Marie, Ontario | P-382 | William Metz Sioux City, IA | |
| Barry Schwartz Cincinnati, OH | P-339 | Don Winters Torrance, CA | |
| Mark Hurt Milledgeville, GA | P-60 | | |
| Kenneth Bryson Sommerville, TX | P-262 | | |

Aircraft Exhaust System Ducting

By: Alan Caddey, Metallurgical Engineer

Alan Caddey joined Renton Coil Spring in June, 1995 after working for Boeing since 1978. Alan has spent his career working with different metals used in critical parts in the aircraft industry. He worked on such projects as the B-2 bomber and most recently has specialized in the titanium technology for the 777, the new High Speed Commercial Transport. Renton Coil Spring Company supplies titanium springs to the aircraft industry.

Low carbon austenitic stainless steels are often used for small aircraft exhaust systems. One caveat used in this application is a recommended upper temperature limit of 1600 degrees F. Above this temperature, several metallurgical mechanisms deteriorate the service life of the component at a **much** higher rate, hence the need to limit the time of the exposure to temperatures above 1600 F. A managed exposure to engine exhaust temperatures, by incorporation of appropriate temperature gauges, can be successfully used to deter exhaust system corrosion, and improve component life expectancy.

Aircraft engines incorporating the use of turbos are more susceptible to high temperature exhaust system exposure than other aircraft. Turbos typically have a maximum recommended temperature of around 1650 F, but experience has shown that depending on the fuel flow settings, the actual temperature can rise to as high as 1730 F. By properly managing the power settings and subsequent exhaust temperatures, the exposure to temperatures above 1600 F can be limited or avoided.

Metallurgically, between 1600 F and about 1770 F, chromium carbide precipitation is very

active at the stainless steel grain boundaries. This leads to depletion of chromium at the boundaries and a **markedly** increased susceptibility to preferential grain boundary (intergranular) attack. This phenomenon is commonly known as sensitization, which leaves the metal susceptible to attack by any corroding (oxidizing) medium, such as hot exhaust gases, (the corrosion rate increases in the presence of water vapor).

In addition, chromium, which protects against corrosion, is selectively oxidized on the surface at elevated temperatures leading to further chromium depletion of the metal. As the overall chromium content falls, so does the corrosion resistance of the metal.

Coupled with these high temperature reactions is the stainless steel reaction with hydrocarbon (carbon containing) exhaust gases at elevated temperature. Carbon is absorbed, and subsequently diffuses into the alloy interior. Carbides of the reactive alloying elements, including chromium, are then precipitated in the steel matrix and grain boundaries, (known as carburization), adding to the overall depletion of chromium, and thereby completing a circle of increasing sensitization and high temperature corrosion. As carburization continues, ductility and impact properties of the metal substrate fall, depending on the degree and distribution of the absorbed carbon.

All of these processes continue over time at temperatures above 1600 F, leading to spalling of heavily carburized surfaces (metal loss) and finally to failure of the stainless steel component. By limiting or eliminating exposure to temperatures above 1600 F, the advantages of using austenitic stainless steels can be fully utilized.

HARTZELL PROPELLER INC.
Distributors and Recommended Repair Facilities
June 1, 1997

DOMESTIC DISTRIBUTORS

Aircraft Propeller Service, Inc.

290 Larkin Drive
Wheeling, Illinois 60090-6456

Attn: John DeJoris
Phone: 847-541-1133
800-323-4130
Fax: 847-541-0176

Aviation Propellers, Inc.

12970 Port Said Road
Opa Locka, Florida 33054

Attn: Tim Gaither
Phone: 305-688-9439
305-688-6030
Fax: 305-681-4236

SUBSIDIARIES:

Aviation Propellers, Inc.

112 Azalea Avenue
Hueytown, Alabama 35020

Attn: Paul Gaither
Phone: 205-491-9133

Aviation Propellers, Inc.

4120 Roush Avenue
Orlando, Florida 32803

Attn: Geoffrey W. Gubbins
Phone: 407-894-2412
Fax: 407-894-0069

Hartzell Service Center

Piqua Airport
5465 West State Route 185
Piqua, Ohio 45356

Attn: Jeff Slattery
Phone: 513-778-4201
Fax: 513-778-4202

Jordan Propeller Service, Inc.

103 East Rhapsody
San Antonio, Texas 78216

Attn: Gary Jordan
Phone: 210-344-3064
Fax: 210-344-9433

SUBSIDIARY:

Jordan Propeller Service, Inc.

6820 Piccadilly
Houston, Texas 77061

Attn: Ben L. Swartz
Phone: 713-643-7464
800-580-7767 (National)
Fax: 713-643-7491

Maxwell Aircraft Service

Crystal Airport
Minneapolis, Minnesota 55429

Attn: Conrad Maxwell
Phone: 612-533-8611
Fax: 612-533-3219

Memphis Propeller Service, Inc.

8500 Summitt Cove
Olive Branch, Mississippi 38654

Attn: Ken Mathews
Phone: 601-895-5282
800-844-7767
Fax: 601-895-6061

Ottosen Propeller & Accessories, Inc.

105 South 28th Street
Phoenix, Arizona 85034

Attn: Don Ottosen
Phone: 602-275-8514
800-528-7551
Fax: 602-275-8594

Piedmont Aviation Services

P. O. Box 525
3817 N. Liberty Street
Winston Salem, North Carolina 27102

Attn: Vestle Widener
Phone: 910-661-5306
Fax: 910-661-5346
Telex: 806438 Piedmontal

HARTZELL PROPELLER INC.
Distributors and Recommended Repair Facilities
June 1, 1997

CANADIAN DISTRIBUTORS

Leavens Aviation Inc.

2555 Derry Road East
Mississauga, Ontario
Canada L4T 1A1

Attn: J. T. Leavens
Phone: 905-678-1234
Fax: 905-678-7028
Telex: 069-68582 Leavens Tor

Western Propeller Co., Ltd.

206 Salteaux Crescent
Winnipeg, Manitoba R3J 3W3

Attn: Dan Rogers
Phone: 204-831-8368
800-665-1336
Fax: 204-831-8401

Hope Aero Propeller & Components, Inc.

2283 Anson Drive
Mississauga, Ontario
Canada L5S 1G6

Attn: Harry Hope
Phone: 905-677-8747
800-268-9900
Fax: 905-677-5935

Western Propeller Co., Ltd.

7940 Yellowhead Trail
Edmonton, Alberta
Canada T5B 1G3

Attn: Bob Spak
Phone: 403-477-3501
800-661-9948
Fax: 403-477-0131

SUBSIDIARIES:

Western Propeller (Pacific) Ltd.

#231, 7080 River Road
Richmond, B.C.
Canada V6X 1X5

Attn: Dave Pallot
Phone: 604-273-4561
800-663-7964
Fax: 604-273-4812

Western Propeller Co., Ltd.

(Corporate Office)

#231, 7080 River Road
Richmond, B.C.
Canada V6X 1X5

Attn: Don Tarnowski
Phone: 604-273-4561
Fax: 604-273-0215

HARTZELL PROPELLER INC.
Distributors and Recommended Repair Facilities
June 1, 1997

INTERNATIONAL DISTRIBUTORS

Aircraft Accessory Services Pty. Ltd.

P. O. Box 745
Salisbury, South Australia
Australia 5108

Attn: Tony Brennand
Phone: 61-8-8258-3033
Fax: 61-8-8258-5083
After Hours No.: 61-8-8395-0915

Aircraft Propeller & Spares (Aust.) Pty. Ltd.

P. O. Box 200
Mentone, Victoria
Australia 3194

Attn: Linton Hayres
Phone: 61-3-9580-2034
Fax: 61-3-9580-0765
Telex: 31251 Apands

CSE Aviation Ltd.

Oxford Airport
Kidlington, OX5 1RA
England

Attn: Trevor Trivett
Phone: 44-1865-844211
Fax: 44-1865-841207
Telex: 83204 AZTEC G

Itochu Aviation Co., Ltd.

Defense and Aerospace
Equipment Department
Defense Systems Division
Tokyo Head Office
5-8, Kita-Aoyama, 2 Chome Minato-Ku
Tokyo 107
Japan

Attn: Nobu Takahashi
Phone: 81-3-3497-8297
Fax: 81-3-5414-8700

C & A Aviation (Pte) Ltd.

Buildings 110/143
East Camp, Seletar Airfield
Singapore 2879

Postal Address:
Jalan Kayu Post Office Box 59
Singapore 9180

Attn: K. H. Chui
Phone: 65-4812233
Fax: 65-4810827
Telex: RS55984 CAAVIA

H & S Aviation Ltd.

Airport Service Road
Portsmouth
Hampshire P03 5PJ
England

Attn: Lee Holloway
Phone: 44-1705-304062
Fax: 44-1705-304060
Telex: 86403 HxS G

Helices Clerici

Santa Maria De Oro 3061
1712 Castelar
Buenos Aires
Argentina

Attn: Hugo Clerici
Phone: 54-1-6235754
Fax: 54-1-7992682
Telex: 21624 ANJOY AR

Hoffmann GmbH & Co., KG.

Kupferlingstr. 9
D-83022 Rosenheim
Germany

Attn: Alexander Vogl,
Sales & Service Dept.
Phone: 49-8031-187828
Fax: 49-8031-187878
Telex: 525811 Hoco D

HARTZELL PROPELLER INC.
Distributors and Recommended Repair Facilities
June 1, 1997

INTERNATIONAL DISTRIBUTORS

MT Propeller Gerd Mühlbauer GmbH

Flugplatz Straubing-Wallmühle
D-94348 Atting
Germany
Postal Address:
Postfach 0720
94307 Straubing
Germany

Attn: Gerd Mühlbauer
Phone: 49-9429-94090
Fax: 49-9429-8432

Diamond Aviaco Ltda.

Av. Santos Dumont
s/n Setor Santa Genoveva
Goiânia - Goiás
74672-420 Brazil

Attn: Abner Wilding
Phone: 55-62-207-1600
Fax: 55-62-207-1073
Telex: 622358 UTAL BR

Norronafly PW+AP A/S

P. O. Box 64
N-1330 Oslo Airport
Norway

Attn: Roar Mikalsen
Phone: 47-67539066
Fax: 47-67590320
Telex: 19339 Rafly N

Placo (PTY) Ltd.

P. O. Box 18017
Rand Airport 1419
Gauteng, South Africa

Attn: B. C. Warren
Phone: 27-11-827-9301
Fax: 27-11-827-3801
Telex: 429656 SA

Technic Aviation

Z. I. Saint Maurice
04100 Manosque
France

Attn: Marc Dubois
Phone: 33-492726648
Fax: 33-492878724
Telex: TECAVIA 405963F

HARTZELL PROPELLER INC.
Distributors and Recommended Repair Facilities
June 1, 1997

RECOMMENDED REPAIR FACILITIES

DOMESTIC

Byam Propeller Service Inc.

4001 North Main Street
Hangar 7 South
Fort Worth, TX 76106

Attn: Karl Byam
Phone: 817-625-0161
Fax: 817-626-0009

CANADIAN

Canadian Propeller Ltd.

462 Brooklyn Street
Winnipeg, Manitoba R3J 1M7
Canada

Attn: Maurice Wills
Phone: 204-832-8679
Fax: 204-888-4696

INTERNATIONAL

Aircraft Accessories & Components Co. Ltd.

P. O. Box 13532
Jeddah 21414
Saudi Arabia

Attn: Mr. Hamad H. Al-Rowais
Phone: 966-2-693-73-47
Fax: 966-2-693-33-96
Telex: 60-15-58 UTSESC SJ

Zimex Aviation Maintenance Ltd.

Zimex Business Aviation Center
PO Box
8058 Zurich-Airport
Switzerland

Attn: Karlheinz Lenzke
Maintenance - Phone: 41 1 815 53 30
Fax: 41 1 815 53 31

East Coast Propellers Pty. Ltd.

Building 641, Klemm Street
Bankstown Airport
Sydney, New South Wales 2200
Australia

Attn: John Marks
Phone: 61-2-9791-0246
Fax: 61-2-9791-0057

Spare Parts - Phone: 41 1 815 53 40
Fax: 41 1 815 53 41

Safe Air Limited

P. O. Box 244, Blenheim Airport
Blenheim, New Zealand

Attn: D. M. Webster
Phone: 64-3-572-8416
Fax: 64-3-572-8846

JAMCO Corporation

HEAD OFFICE:
Yukio Kobayashi, General Manager
Marketing Department V
6-11-25, Osawa, Mitaka City
Tokyo, 181 Japan

Attn: Norihiko Miyairi, Exec. V. P.
Phone: 81-422-33-1321
Fax: 81-422-32-6998
Telex: 2822553 (JAMTOK)

West Coast Propellers P/L

Unit 6/10 Whyalla Street
Willeton, Western Australia 6155
Postal Address:
P. O. Box 3111
Jandakot, Western Australia 6164

Attn: Stephen Ashley
Phone: 61-9-354-4171
Fax: 61-9-354-4113

SHOP LOCATION:

Sendai Aircraft Maintenance
Division 60
Sintaku, Shimonogo Iwanuma
Miyagi, Japan

Phone: 81-223-22-2126
Fax: 81-223-22-6009

**AlliedSignal
Turbochargers**

Aircraft Distributor List

20326
Aviall Services, Inc.
P.O.Box 7086 B-Bldg.
Dallas, TX 75209
972-406-2026
972-406-2071 fax

21175
AMR Combs/A P I
3778 Distriplex Drive N.
Memphis, TN 38181
800-950-0111
901-345-1832
800-950-1411 fax

20098
Arizona Aircraft Access.
5103 E. Roadrunner
Mesa, AZ 58205
800-678-9912
602-833-5812
602-396-3727 fax

20333
AVSCO
5125 BlaLock Industrial Blvd
Atlanta, GA 30320
404-765-1826
404-765-1896 fax
800-241-6850

21123
AAR Cooper Aviation
2149 E. Pratt Blvd.
Elk Grove Village, IL 60007
847-364-2600
800-654-4944
847-364-0357 fax

21180
Flightcraft, Inc.
7505 N.E. Airport Way
Portland, OR 97218
503-331-4281
503-282-1200 fax

20394
Garrett GMBH
Frankfurter-Strasse 51
6096 Raunheim/Main
West Germany
011-496-1422-4051

20479
Mattituck Aviation
Airway Drive
Mattituck, NY 11952
516-298-8330
800-624-6680
516-298-8412 fax

20355
Normalair-Garrett
14 Riverside Road
Chipping Norton NSW 2170
Sydney, Australia
011-612-9755-3311
011-612-9724-7909 fax

20341
Omaha Airplane Supply
Eppley Field/P.O. Box 19084
Omaha, NB 68119
402-422-6666
800-228-9400
402-341-7895 fax

25767
Pacific Continental Engines
160410 Arminta Street
Van Nuys, CA 91406
818-781-4947
818-781-0860 fax

21134
The Parts Exchange, Inc.
3545 G Centre Circle Dr.
Ft. Mill, SC 29715
803-548-2665
800-528-0390
803-548-6360 fax

20840
Superior Air Parts, Inc.
14280 Gills Road
Addison, TX 75001
972-663-2614
800-487-4884
972-702-8723 fax

A 414 Fatal Accident in Ohio

Hillsboro, Ohio, April 8, 1997.

According to witnesses, a Cessna 414 having mechanical problems burst into flames just before crashing into a mobile home about 60 miles southwest of Columbus.

According to the *Columbus Dispatch*, there were seven people inside the mobile home and all of them escaped without injury. The pilot and passenger of the 414 were killed instantly and the aircraft was a total loss.

NTSB investigators pointed to a failed exhaust system, that had been patched several times, leading to failure of the cross-feed fuel lines aft of the firewall at the rear of the engine compartment as a preliminary cause.

In the last 24 months, we have been told that there have been 12 turbo twin Cessna accidents resulting in 24 plus fatalities. This is causing the NTSB to pressure the issuance of a new Airworthiness Directive by the FAA. We are told that AOPA, The Cessna Pilots Association and The Twin Cessna Flyer will be included in the meetings leading to this AD.

There are two ways an AD can be issued. The first allows a period of comment from owners, mechanics and others in the field as a result of a Notice of Proposed Rules Making. The second is the issuance of an emergency AD. This does not allow for the comment period.

There are a lot of ideas as of this writing on how this subject will be handled. If you own a turbo Twin Cessna, you have probably received the letter from Mike Busch of the CPA informing you of the problem/s at hand. We share in his view that the best action by any turbo twin Cessna owner at this time would be a thorough inspection of the

complete exhaust system including removal of any suspected parts for a more thorough inspection. Also pay strict attention to the aircraft structure close to the exhaust such as engine mounting rails, fire walls and canted bulkheads inside the nacelle. Any defective part/s should be replaced or repaired by a Certified Repair Station that specializes in weld repair before further flight.

The worse case would be for the FAA to ground the entire fleet of turbo twin Cessna aircraft until an inspection, such as the one above, is completed. While this has not gone to the point of grounding the fleet yet, some sort of action is inevitable. No one can second guess the FAA, but it would be a safe bet that the above inspection, by qualified people, along with a well-written log book entry could save you a lot of hassle when the action finally is printed and every owner has to take action at the same time.

Parts, such as engine mounting rails are not available at this time and we find about 20% of the turbo twins need either new rails or rail sections. There is no authorized repair of any kind allowed on the engine mounting rails except through an engineering order from Cessna.

Shoddy maintenance and sub-standard repairs have led to exhaust failures. Exhaust failures can lead to accidents. Accidents lead to loss of lives.

The NTSB has a long list of accidents where they can definitely pin down the cause as exhaust failure leading to on-board fires in flight due to cross-feed fuel line/s failure.

We will keep you posted as we get information.